

Pewetration into Confined Space Connected to COa Cylinder(5)

Manual RAM 42 H XI


BEST AVAILABLE COPY


R12

Popy

Hollow inset for Lance Connection Cylinder Insertion
Handles for Graspins
Heavy Steel Cylinder For Kinstic Energy Transfer to Lance

 $\Box$ 






PEST AVAILABLE COPY

YAOD 318AJIAVA T23-Long Ram End View


- 11

- Handle Side View Kig 96 Short RAM Rocess For Holding Lance Dr Handle Fig ga Recess For Holding Lance



BASIC AIRCRAFT System

1.g 10



JEST AVAILABLE COPY

